

Project Info



18 / 01 / 2012



CC13 & CC8
batch rolls



240sqm CC8
10 sqm CC13



Transverse layer



Aysen, XV region
Chile



Mendez Soluciones
& Polytrade



CC used for time critical
remedial work of a fish
farm, lining a cracked
and dilapidated concrete
reservoir.



Reconditioned fish farm reservoir which was restocked 1 day after CC installation



Dilapidated concrete reservoir



Unrolling CC8 batched rolls into position



Fixing CC to the existing concrete substructure



Lined concrete reservoir with sealed joints



Refilling the basin to hydrate the CC



Completed reconditioned fish reservoir

